NON-STANDARD INLET

FAILING BRICK STRUCTURE

W. RANDOLPH STREET (32.08' W)

INEFFICIENT INLET

NO INLET AT CORNER

BRICK STRUCTURE

DISCHARGE LOCATION

BAYARD STREET (32.08' W)

N. 5TH STREET (38.5' W)

ALLEY (20' W)

SEWAGE IN STORM SEWER

LAWRENCE STREET (32.08' W)

N. 4TH STREET (38.5' W)

N. 3RD STREET (38.5' W)

EXISTING CURB INLET

N. 2ND STREET (38.5' W)

MONTGOMERY STREET (32.08' W)

60' 0 60' 120'

GRAPHIC SCALE

DATE PREPARED
01/16/2018

ROUTE
.

STATE
MO

DISTRICT
.

SHEET NO.

COUNTY
ST. CHARLES

JOB NO.
160886

CONTRACT ID.
17STM9

PROJECT NAME
2ND/LAWR. STORM

SHEET NAME
EXHIBIT A

DATE	DESCRIPTION
X	X

CITY OF ST. CHARLES
DEPARTMENT OF PUBLIC WORKS
200 N. SECOND STREET ROOM 202
ST. CHARLES, MO 63301
636.949.3237

THOUVENOT, WADE & MOERCHEN, INC. ST. CHARLES OFFICE
CONSULTING ENGINEERING
GEOSPATIAL SERVICES

400 N. 5TH STREET, SUITE 101
ST. CHARLES, MISSOURI 63301
TEL. (636) 724-8300

PROF. LICENSE NUMBER
MO. PROF. ENGR. CORP. NC 001528
MO. LAND SURVEYING CORP. NC 000346